MCAS CHERRY POINT SAFETY OFFICE **SAFETY WARNING** DSN 582-2730/COMM (252)466-2730

CPSW001-2023

* **DO YOU WALK BY** A TIPPING, **CRUSHING, OR COLAPSING HAZARD DAILY? DID YOU KNOW ALL RACK COLUMNS SHALL BE ANCHORED TO** THE FLOOR WITH **ANCHOR BOLTS** AND LABELED WITH THE LOAD **RATING PER THE MANUFACTURERS** SPECIFICATIONS?

S

W

R

Ν

Ν

G

S

Α

W

Α

R

N

Ν

G



INSPECT YOUR SHELVING UNITS FOR PROPER LOAD RATINGS, ANCHORING AND ANY CORROSION OR PHYSICAL DAMAGE THAT **COULD JEOPARDIZE THE INTEGRITY OF THE UNIT!**

The bottom of all columns shall be furnished with column base plates, as specified in Section 7.1. All rack columns shall be anchored to the floor with anchor bolts, which shall **SAFETY WARNING** be designed in accordance with Section 7.3.

SHELVING UNITS



References:

ANSI MH16.1: 2012 1.4.7 COLUMN BASE

PLATES AND ANCHORS

VA/

Δ

R

Ν

Ν

G

S

W

Α

R

Ν

Ν

G